



# Appendix 3.1-6

## Elevator Pit Investigation

---

**Subject:**

RE: [External] Fwd: Freight car pit

---

**From:** Vito Corbo <[vcorbo@nassaucoliseum.com](mailto:vcorbo@nassaucoliseum.com)>

**Sent:** Friday, February 9, 2024 11:17 AM

**To:** Joseph Zino <[jzino@nassaucoliseum.com](mailto:jzino@nassaucoliseum.com)>

**Subject:** Freight car pit

**Importance:** High

Joe,

As per yesterday's Inspection with Otis Elevator, they inspected and tested to ensure that the hydraulic shaft and shaft seal was not compromised (leaking or burr's). The shaft, seal and the hydraulic recovery pump are mechanically in good operational condition.

After future investigation to figure out how the water was entering the shaft, the Otis supervisor was able to point out that the shaft is in a sleeve which allows water from the earth to enter and out of that shaft sleeve.

Please see recent photo of shaft and sleeve.

Thank you,

VC

**VITO CORBO**

Chief Engineer

516-560-9572 (Cell)

516-654-8172 (Direct)

[vcorbo@nassaucoliseum.com](mailto:vcorbo@nassaucoliseum.com)

[www.NassauColiseum.com](http://www.NassauColiseum.com)

<image001.png>



[The information contained in this e-mail message is intended only for the use of the individual or entity named above. If the reader of this message is not the intended recipient, or is not the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify us by telephone or reply by e-mail and then promptly delete the message. Thank you.]